

*Ethylene Unit Pyrolysis Furnace  
Opportunity  
& Strategic Improvements*



Sharipah Jalil - Presenter

Karl Kolmetz

Charles D. Nolidin

Cyron Anthony Soyza


# *Pyrolysis Furnace Opportunity & Strategic Improvements*

- Furnace layout
- Radiant Coil Elongation
- Convection tube bowing
- Shadow box hot-spots
- U-bend erosion
- Radiant Coil Thermal shock
- Conclusion

## *Unit 2 Furnace Layout*

- 6 furnaces (12 Zones)
- 10 Naphtha Zones & 2 Recycle Zones
- Common Convection Heat Recovery Bank for two zones with Induced draft fan
- Radiant products cooled by quench coolers producing SHP (105 bar) steam
- Effluent sent to Quench Section

# Furnace Layout




# *1st Opportunity : Coil Elongation - scenario*




- Creep rate is between 60 - 78 mm per year in one zone example
- Coil needs shortening approx. every 5 years
- Recycle zones are fired harder to achieve optimum yield causing higher Tube Metal Temperature (TMT)

# *Coil Elongation*

## *- theory*




- Flame impingement
  - burner tip blockage
- Heat maldistribution
  - uneven firing
  - mixture of old & new burner tips
- ASWT
  - average sound wall thickness
  - thicker walls more prone to creep



# Coil Elongation

## -a glance

Creep amount  
Tube no.



# *Coil Elongation*

## *-current & future mitigation*

- Burner tip cleaning and maintenance
- Coil elongation monitoring
- Future:-

Kubota MERT tubes -  
lowers TMT's by  
increasing heat transfer


Auto Excess O2 control -  
lowers firing needs





# *2nd Opportunity : Convection Coil Bowing - scenario*

- Bottom section of convection bank bowed approx. 30cm
- Cracks at weldment from mixing header to inlet manifold



# *Convection Coil Bowing*

## *- theory*



- Zone mainly recycle feed
- Recycle cracking requires higher Coil Outlet Temperature for conversion
- Excess heat recovered in convection

# *Convection Coil Bowing*

## *- theory*



- Too much excess heat raises XOT temperature which initiates premature cracking
- Metallurgy limits promotes creep and expansion

# *Convection Coil Bowing* *- a glance*



# *Convection Coil Bowing -current & future mitigation*

## Current

- Stress analysis required on piping and full understanding of metallurgy limits
- Spring hanger adjusted to relief piping stress
- Bowed convection coils replaced
- Secondary steam injection optimized

# *Convection Coil Bowing -current & future mitigation*



## **Future**

- Upgrading of crossover and convection material
- protect convection coils by insulative material


## *3rd Opportunity*

### *- Shadow Box Hotspots- scenario*



- Insulation around radiant outlet replaced and shadow box plates upgraded to SS304 after turnaround
- Hotspots detected on shadow box during thermograph survey


## *- Shadow Box Hotspots- scenario*

- 
- Plates deteriorated and warped
  - Some insulation cladding melted
  - Insulation material noticed on firebox floor




# *Shadow Box Hotspots* *- theory*

- Heat escaping shadow box due to improperly installed insulation
- Gaps existed which allowed heat to escape the radiant box




# *Shadow Box Hotspots* *- a glance*

**The Past**



# *Shadow Box Hotspots* *- a glance*

## **The Present**



# *Shadow Box Hotspots*

## *- current & future mitigation*




- Insulation stuffed from outside and inside
- Reengineer installation procedure and shadow box plate

# *Shadow Box Hotspots*

## *- current & future mitigation*

- Final assessment of insulation integrity must be carried out each time furnace insulation replaced



# *SLE U-Bend Erosion*

## *- scenario*



- Thinning 1mm per year at the inlet sweep bend
- Change U-bend if thickness drops below 3.5 mm from initial of 8.8mm
- Replacement every 3 years


# *SLE U-Bend Erosion*

## *- theory*



- Erosion main contributing factors include solid presence, material specification and flow path geometry
- Initially, gradual transition in flow section and shallow-angle intersections was enough to mitigate erosion


# *SLE U-Bend Erosion* *- theory*





# *SLE U-Bend Erosion*

## *- theory*



# *SLE U-Bend Erosion* *- a glance*



# *SLE U-Bend Erosion*

## *- current & future mitigation*

- Inlet and outlet sweeps alternated to even out erosion effect
- Ultrasonic Thickness Scanning (UTS) to detect thinning and make replacements
- Modify U-bend to increase integrity of pipe inline with increasing flow turbulence

# *5th Opportunity*


## *Radiant Coil Thermal Shock -theory*



- Coke formation is an undesirable feature of the cracking process
- The carbon coats the inside surface of the tubes, increasing in thickness

# *Radiant Coil Thermal Shock -theory*

- The coke layer can reach  $> 10$  mm thickness depending on the type of feedstock and severity



# *Radiant Coil Thermal Shock -theory*

- The thickness of the coke is a function of the TMT



# *Radiant Coil Thermal Shock* *-theory*



- Coke layer is hard, relatively brittle, and has a lower coefficient of thermal expansion than the tube metal
- With coke presence during sudden shutdown two things can happen:-
  - ~ coke falls off - spalling that leads to tube blockage
  - ~ coke remains - coil splitting due to it's faster rate of contraction

# *Radiant Coil Thermal Shock* *-scenario*




- 1st Dec 01 power supply interruption due to national power grid
- Steam from utilities lost during power outage
- Furnace damper goes to minimum opening to avoid heat loss
- Bottom air register dampers manually closed



# Radiant Coil Thermal Shock -scenario

- Coil temperature drops 100 ~200 °C in 1st hour after trip
- Allowable temp. drop is <80 °C



# *Radiant Coil Thermal Shock -scenario*



- Difference in cooling rate depends on amount of coke and insulation condition
- Coils inspected after temperature almost ambient : ~ 70 coils needed replacement

# *Radiant Coil Thermal Shock -scenario*



# *Radiant Coil Thermal Shock -scenario*



# *Radiant Coil Thermal Shock -mitigation*



- Decoke End Of Run tubes as soon as possible before shutting down furnaces
- Avoid unnecessarily furnace emergency shutdowns
- Ensure reliability of Uninterrupted Power Supply (UPS)

# *Pyrolysis Furnace Opportunity & Strategic Improvements*

## **Conclusion**

- Reviewed Furnace layout
- Reviewed Furnace opportunities
- Reviewed current and future improvement strategies

# *Pyrolysis Furnace Opportunity & Strategic Improvements*

## **Conclusion**

- Implemented improvements to reduce Equipment Opportunity Losses
- Prolonged life and operability of equipment, thus reducing downtime and maintenance cost
- Further opportunities to improve are being evaluated



Thank You

Q & A